Capital Fund Program - Five-Year Action Plan

Status: Approved Approved Date: 05/29/2024 Approved By: NORMAN, KARA 10/31/2026

Part I: Summary								
PHA Name: Fort Fairfield Housing Authority		Locality (City/County & State) X Original 5-Year Plan		Revised 5-Year Plan (Revision No:)		
PHA Number: ME002								
Α.	Development Number and Name	Work Statement for Year 1 2024	Work Statement for Year 2 2025	Work Statement for Year 3 2026	Work Statement for Year 4 2027	Work Statement for Year 5 2028		
	BORDERVIEW HOMES (ME002000001)	\$274,083.00	\$257,184.00	\$257,184.00	\$257,184.00	\$257,184.00		

Part II: Supporting Pages - Physical Needs Work Statements (s)

Work Statement for Year

Identifier	Development Number/Name	General Description of Major Work Categories	Quantity	Estimated Cos
	BORDERVIEW HOMES (ME002000001)			\$274,083.00
ID0040	Borderview Bathroom Upgrade(Dwelling Unit-Interior (1480)-Bathroom Counters and Sinks,Dwelling Unit-Interior (1480)-Bathroom Flooring (non cyclical),Dwelling Unit-Interior (1480)-Commodes,Dwelling Unit-Interior (1480)-Electrical,Dwelling Unit-Interior (1480)-Plumbing,Dwelling Unit-Interior (1480)-Tubs and Showers)	Removal of old bathroom and install of new shower/tub, sheetrock, flooring, plumbing electrical, vanity, toilet, shower heads and paint		\$16,266.00
ID0011	Operations(Operations (1406))	Maintenance to 81 Public Housing Units and Properties		\$22,926.22
ID0035	Borderview Register Upgrade(Dwelling Unit-Interior (1480)-Other)	remove old registers and replace with new ones		\$40,000.00
ID0016	Fields Lane I and III Patio Doors(Dwelling Unit-Exterior (1480)-Exterior Doors)	install new sliding patio doors at Fields Lane I and III		\$58,510.78
D0017	Install new Patio Dividers Fields Lane I (Dwelling Unit-Exterior (1480)-Decks and Patios)	Install new vinyl or composite patio dividers and remove the old ones and install new patio from cement and carpet to asphalt		\$118,000,00
D0044	Fields Lane I and III windows(Dwelling Unit-Exterior (1480)-Windows)	Repair or install new windows at Fields Lane I and III		\$18,380.00

Part II: Sup	Part II: Supporting Pages - Physical Needs Work Statements (s)							
Work Statement for Year 1 2024								
Identifier	Development Number/Name		General Description of Major Work Categories	Quantity	Estimated Cost			
	Subtotal of Estimated Cost				\$274,083.00			

Part II: Supporting Pages - Physical Needs Work Statements (s)

Work Statement for Year 2

Identifier	Development Number/Name	General Description of Major Work Categories	Estimated Cost	
	BORDERVIEW HOMES (ME002000001)			\$257,184.00
ID0015	Fields Lane I and III windows(Dwelling Unit-Exterior (1480)-Windows)	Repair or install new windows at Fields Lane I and III		\$135,266.00
ID0018	Operations(Operations (1406))	Maintenance on 81 Public Housing units and properties		\$18,918.00
ID0022	Removal of Carpet and installation of Plank Flooring (Dwelling Unit-Interior (1480)-Flooring (non routine))	Removal of carpet in LR and Bedrooms, install new plank flooring		\$88,000.00
ID0023	New Roof For Garage(Non-Dwelling Exterior (1480)-Roofs)	install a metal roof for Fields Lane Garage		\$15,000.00
	Subtotal of Estimated Cost			\$257,184.00
	Subtotal of Estimated Cost			\$257,184.00

Part II: Supporting Pages - Physical Needs Work Statements (s)

Work Statement for Year 3

Identifier	Development Number/Name	General Description of Major Work Categories	Estimated Cost	
	BORDERVIEW HOMES (ME002000001)			\$257,184.00
ID0024	Hillcrest Parking Lot Upgrade(Non-Dwelling Site Work (1480)-Asphalt - Concrete - Paving)	repave the parking lot at Hillerest Estates		\$100,000.00
ID0029	Install New Windows at Hillcrest Estates (Dwelling Unit-Exterior (1480)-Windows)	Install new windows at Hillcrest Estates in units and through building		\$143,266.00
ID0031	Operations (Operations (1406))	Maintenance for 81 Public Housing Units		\$13,918.00
	Subtotal of Estimated Cost			\$257,184.00

Part II: Supporting Pages - Physical Needs Work Statements (s)

Work Statement for Year 4

Identifier	Development Number/Name	General Description of Major Work Categories	Quantity	Estimated Cost
8	BORDERVIEW HOMES (ME002000001)			\$257,184.00
ID0037	Borderview Bathroom Upgrade(Dwelling Unit-Interior (1480)-Bathroom Counters and Sinks, Dwelling Unit-Interior (1480)-Bathroom Flooring (non cyclical), Dwelling Unit-Interior (1480)-Commodes, Dwelling Unit-Interior (1480)-Electrical, Dwelling Unit-Interior (1480)-Plumbing, Dwelling Unit-Interior (1480)-Tubs and Showers)	Removal of old bathroom and install of new shower/tub, sheetrock, flooring, plumbing electrical, vanity, toilet, shower heads and paint		\$158,266.00
1D0038	Borderview Flooring(Dwelling Unit-Interior (1480)-Flooring (non routine))	Removal of old tile in downstairs part of unit, kitchen, living room, and downstairs bedroom		\$85,000.00
ID0039	Operations(Operations (1406))	Maintenance and management expenses for 81 PH units		\$13,918,00
	Subtotal of Estimated Cost	*		\$257,184.00

Part II: Supporting Pages - Physical Needs Work Statements (s)

Work Statement for Year 5

Identifier	Development Number/Name	General Description of Major Work Categories	Quantity	Estimated Cost
	BORDERVIEW HOMES (ME002000001)			\$257,184.00
ID0013	Hillcrest Siding Upgrade(Dwelling Unit-Exterior (1480)-Siding)	upgrade the painted areas on the building with Vinyl siding		\$35,000.00
ID0020	Borderview Living Room Install (Dwelling Unit-Interior (1480)-Electrical)	Install Living Room Lights at Borderview Homes		\$25,000.00
1D0041	Borderview Bathroom Upgrade(Dwelling Unit-Interior (1480)-Bathroom Counters and Sinks, Dwelling Unit-Interior (1480)-Bathroom Flooring (non cyclical), Dwelling Unit-Interior (1480)-Commodes, Dwelling Unit-Interior (1480)-Electrical, Dwelling Unit-Interior (1480)-Plumbing, Dwelling Unit-Interior (1480)-Tubs and Showers)	Removal of old bathroom and install of new shower/tub, sheetrock, flooring, plumbing electrical, vanity, toilet, shower heads and paint		\$90,000.00
ID0042	Borderview Flooring(Dwelling Unit-Interior (1480)-Flooring (non routine))	Removal of old tile in downstairs part of unit, kitchen, living room, and downstairs bedroom		\$93,266.00
1D0043	Operations(Operations (1406))	Maintenance and management expenses for 81 PH units		\$13,918.00
	Subtotal of Estimated Cost			\$257,184.00

()							
				5			
	¥						
		15	E E		a.	11	